



Arm CoreLink CI-700 Coherent Interconnect

Software Developer Errata Notice

Date of issue: July 23, 2024


Non-Confidential

Document version: 13.0

Copyright © 2020-2024 Arm® Limited (or its affiliates). All rights reserved.

Document ID: SDEN-1780265

This document contains all known errata since the r0p0 release of the product.



This document is Non-Confidential.

Copyright © 2020-2024 Arm® Limited (or its affiliates). All rights reserved.

This document is protected by copyright and other intellectual property rights.

Arm only permits use of this document if you have reviewed and accepted Arm's Proprietary notice found at the end of this document.

This document (SDEN_1780265_13.0_en) was issued on July 23, 2024.

There might be a later issue at <http://developer.arm.com/documentation/SDEN-1780265>

Inclusive language commitment

Arm values inclusive communities. Arm recognizes that we and our industry have used language that can be offensive. Arm strives to lead the industry and create change.

If you find offensive language in this document, please email terms@arm.com.

Feedback

Arm welcomes feedback on this product and its documentation. To provide feedback on Arm CoreLink CI-700 Coherent Interconnect, create a ticket on <https://support.developer.arm.com>.

To provide feedback on the document, fill the following survey:
<https://developer.arm.com/documentation-feedback-survey>.

Contents

Introduction	4
Scope	4
Categorization of errata	4
Change Control	5
Errata summary table	7
Errata descriptions	9
Category A	9
Category A (rare)	9
Category B	10
1926789 SECC error on ABF operation can cause coherency failures for other memory addresses	10
2243907 WriteZero transactions can deadlock when not supported downstream of MTSX	12
2301815 MTE Tag Cache transaction queue may hang	13
3013639 Write Stash can cause multi-copy atomicity issue	14
3300058 More than two XY route override can result in deadlocks	16
3658369 MPAM MSMON_CSU.NRDY not cleared in a finite time	17
Category B (rare)	17
Category C	18
2177971 HN-I RAS syndrome registers do not capture correct opcode	18
2741290 RAS HN-I and SBSX ERRGSR registers do not capture correct device instance information	20
3013642 Incorrect TagMatch response on partial writes with MTE Match	21
3031700 Debug reads with simultaneous coherent traffic or dynamic power transitions can cause deadlock	22
3114501 Transactions targeting the HN-D AXI interface might be stalled by a continuous stream of CMN configuration transactions	23
3197819 HN-I ERRADDR_NS.NS field is incorrect	24
3279821 HN-F Non-Secure RAS events may be reported in Secure error records	25
Proprietary notice	26
Product and document information	28
Product status	28
Product completeness status	28
Product revision status	28

Introduction

Scope

This document describes errata categorized by level of severity. Each description includes:

- The current status of the erratum.
- Where the implementation deviates from the specification and the conditions required for erroneous behavior to occur.
- The implications of the erratum with respect to typical applications.
- The application and limitations of a workaround where possible.

Categorization of errata

Errata are split into three levels of severity and further qualified as common or rare:

Category A	A critical error. No workaround is available or workarounds are impactful. The error is likely to be common for many systems and applications.
Category A (Rare)	A critical error. No workaround is available or workarounds are impactful. The error is likely to be rare for most systems and applications. Rare is determined by analysis, verification and usage.
Category B	A significant error or a critical error with an acceptable workaround. The error is likely to be common for many systems and applications.
Category B (Rare)	A significant error or a critical error with an acceptable workaround. The error is likely to be rare for most systems and applications. Rare is determined by analysis, verification and usage.
Category C	A minor error.

Change Control

Errata are listed in this section if they are new to the document, or marked as "updated" if there has been any change to the erratum text. Fixed errata are not shown as updated unless the erratum text has changed. The [errata summary table](#) identifies errata that have been fixed in each product revision.

July 23, 2024: Changes in document version v13.0

ID	Status	Area	Category	Summary
3658369	New	Programmer	Category B	MPAM MSMON_CSU.NRDY not cleared in a finite time

April 02, 2024: Changes in document version v12.0

ID	Status	Area	Category	Summary
3300058	New	Programmer	Category B	More than two XY route override can result in deadlocks
3197819	New	Programmer	Category C	HN-I ERRADDR_NS.NS field is incorrect
3279821	New	Programmer	Category C	HN-F Non-Secure RAS events may be reported in Secure error records

December 15, 2023: Changes in document version v11.0

ID	Status	Area	Category	Summary
3114501	New	Programmer	Category C	Transactions targeting the HN-D AXI interface might be stalled by a continuous stream of CMN configuration transactions

October 13, 2023: Changes in document version v10.0

No new or updated errata in this document version.

August 18, 2023: Changes in document version v9.0

ID	Status	Area	Category	Summary
3013639	New	Programmer	Category B	Write Stash can cause multi-copy atomicity issue
3013642	New	Programmer	Category C	Incorrect TagMatch response on partial writes with MTE Match
3031700	New	Programmer	Category C	Debug reads with simultaneous coherent traffic or dynamic power transitions can cause deadlock

September 21, 2022: Changes in document version v8.0

ID	Status	Area	Category	Summary
2741290	New	Programmer	Category C	RAS HN-I and SBSX ERRGSR registers do not capture correct device instance information

April 11, 2022: Changes in document version v7.0

No new or updated errata in this document version.

February 11, 2022: Changes in document version v6.0

ID	Status	Area	Category	Summary
2301815	Updated	Programmer	Category B	MTE Tag Cache writes may be dropped

January 07, 2022: Changes in document version v5.0

ID	Status	Area	Category	Summary
2301815	New	Programmer	Category B	MTE Tag Cache writes may be dropped

September 27, 2021: Changes in document version v4.0

ID	Status	Area	Category	Summary
2243907	New	Programmer	Category B	WriteZero transactions can deadlock when not supported downstream of MTSX
2177971	New	Programmer	Category C	HN-I RAS syndrome registers do not capture correct opcode

September 25, 2020: Changes in document version v3.0

No new or updated errata in this document version.

August 21, 2020: Changes in document version v2.0

ID	Status	Area	Category	Summary
1926789	New	Programmer	Category B	SECC error on ABF operation can cause coherency failures for other memory addresses

March 25, 2020: Changes in document version v1.0

No errata in this document version.

Errata summary table

The errata associated with this product affect the product versions described in the following table.

ID	Area	Category	Summary	Found in versions	Fixed in version
1926789	Programmer	Category B	SECC error on ABF operation can cause coherency failures for other memory addresses	r0p0	r1p0
2243907	Programmer	Category B	WriteZero transactions can deadlock when not supported downstream of MTSX	r0p0, r1p0, r1p1, r2p0	r1p2, r2p1
2301815	Programmer	Category B	MTE Tag Cache writes may be dropped	r0p0, r1p0, r1p1, r1p2, r2p0	r1p3, r2p1
3013639	Programmer	Category B	Write Stash can cause multi-copy atomicity issue	r0p0, r1p0, r1p1, r1p2, r1p3, r2p0, r2p1, r2p2, r3p0, r3p1	Open
3300058	Programmer	Category B	More than two XY route override can result in deadlocks	r0p0, r1p0, r1p1, r1p2, r1p3, r2p0, r2p1, r2p2, r3p0, r3p1	Open
3658369	Programmer	Category B	MPAM MSMON_CSU.NRDY not cleared in a finite time	r0p0, r1p0, r1p1, r1p2, r1p3, r2p0, r2p1, r2p2, r3p0, r3p1	Open
2177971	Programmer	Category C	HN-I RAS syndrome registers do not capture correct opcode	r0p0, r1p0, r1p1, r1p2, r1p3	r2p0
2741290	Programmer	Category C	RAS HN-I and SBSX ERRGSR registers do not capture correct device instance information	r0p0, r1p0, r1p1, r1p2, r1p3, r2p0, r2p1, r2p2, r3p0, r3p1	Open
3013642	Programmer	Category C	Incorrect TagMatch response on partial writes with MTE Match	r0p0, r1p0, r1p1, r1p2, r1p3, r2p0, r2p1, r2p2, r3p0, r3p1	Open
3031700	Programmer	Category C	Debug reads with simultaneous coherent traffic or dynamic power transitions can cause deadlock	r0p0, r1p0, r1p1, r1p2, r1p3, r2p0, r2p1, r2p2, r3p0, r3p1	Open
3114501	Programmer	Category C	Transactions targeting the HN-D AXI interface might be stalled by a continuous stream of CMN configuration transactions	r0p0, r1p0, r1p1, r1p2, r1p3, r2p0, r2p1, r2p2, r3p0, r3p1	Open

ID	Area	Category	Summary	Found in versions	Fixed in version
3197819	Programmer	Category C	HN-I ERRADDR_NS.NS field is incorrect	r0p0, r1p0, r1p1, r1p2, r1p3, r2p0, r2p1, r2p2, r3p0, r3p1	Open
3279821	Programmer	Category C	HN-F Non-Secure RAS events may be reported in Secure error records	r0p0, r1p0, r1p1, r1p2, r1p3, r2p0, r2p1, r2p2, r3p0, r3p1	Open

Errata descriptions

Category A

There are no errata in this category.

Category A (rare)

There are no errata in this category.

Category B

1926789

SECC error on ABF operation can cause coherency failures for other memory addresses

Status:

Affects: CI-700

Fault Type: Programmer Category B

Fault Status: Present in r0p0. Fixed in r1p0.

Description:

CI-700 supports Address Based Flush (ABF) where upper and lower system addresses can be programmed and then request a hardware-based engine to flush out that address range from all System Level Caches (SLC). This ABF state machine works in the presence of other memory requests.

Single-bit ECC errors on the ABF accesses can corrupt the CMN Snoop Filter state, and result in coherency failures for other unrelated memory addresses.

Configurations Affected:

Any configuration of CI-700 where ABF is used.

Conditions:

This bug appears when following three conditions occur:

- SLC address from flush set/way is outside ABF programmed range AND
- SLC Tag read has single bit ECC error AND
- There is independent request in pipeline N cycles ahead of ABF request (where N is SLC_TAG_RAM_LATENCY)
In this case, ABF request corrupts SF vector for independent request that's ahead of ABF causing coherency failure.

Implications:

The ABF flush sequence can cause coherency fails for unrelated memory addresses during the sequence.

WorkAround:

Use the CI-700 power management features to flush the SLC, flushes the full SLC contents vs. the upper/lower range.

2243907**WriteZero transactions can deadlock when not supported downstream of MTSX****Status**

Affects: CI-700

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r1p0, r1p1, r2p0. Fixed in r1p2, r2p1.

Description

If AXI WriteZero transactions are not supported downstream of MTSX, CI-700 can be configured to synthesize WriteZero data. Interactions between sequences of WriteZero transactions that synthesize data can cause write transactions to deadlock.

Configurations affected

CI-700 configurations where MTSX AXI WriteZero propagation is not enabled and RN-Fs issue WriteZero CHI transactions.

Conditions

- MTE is enabled AND
- MTSX is configured to synthesize WriteZero data AND
- Sequences of WriteZero transactions where the writes are issued to AXI and internal MTE logic out of order

Implications

If the preceding conditions are met, WriteZero transactions can deadlock.

Workaround

Disable WriteZero in the RN-F. Arm CPUs support WriteZero disable. For example:

- Cortex-A710 core, CPUACTLR5_EL1.l2spr_writezero_dis[29] = 1
- Cortex-X2 core, CPUACTLR5_EL1.l2spr_writezero_dis[29] = 1
- Cortex-A510, IMP_CPUECTLR_EL1.wzdis[18] = 1

Note that disabling WriteZero in Arm CPUs may reduce WriteZero performance.

2301815

MTE Tag Cache transaction queue may hang

Status

Affects: CI-700

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r1p0, r1p1, r1p2, r2p0. Fixed in r1p3, r2p1.

Description

Transactions with MTE enabled that share the same tag DRAM address can lead to a hang in the transaction tracking queue.

Configurations affected

CI-700 configurations with MTSX configured with a Tag Cache.

Conditions

- MTE is enabled AND
- 2 MTE Tag requests to the same 32*64B memory region AND
- MTE Tag Cache enabled AND
- Sufficient traffic leading to a Tag Cache eviction with matching tag DRAM address

Implications

Either of the following:

- Hang: the MTU transaction tracking queue is hung and no forward progress can occur. A reset is required.
- Tag data corruption: the youngest MTE Tag data can be overwritten by the next youngest write, one of the write data is dropped.

Workaround

Disable the MTSX MTE Tag Cache.

3013639

Write Stash can cause multi-copy atomicity issue

Status

Affects: CI-700

Fault Type: Programmer Category B

Fault Status: r0p0, r1p0, r1p1, r1p2, r1p3, r2p0, r2p1, r2p2, r3p0, r3p1. Open.

Description

CHI and AXI Write Stash operations can incorrectly get early completion before snooping is complete causing multi-copy atomicity issues.

For example, an RN-I or RN-D PCI MSI write issued after a Write Stash can result in the CPU having an older or stale copy of the Write Stash data at the time of the MSI interrupt.

Another example is an RN-I or RN-D write flag issued after completion of the Write Stash, the CPU can observe the flag update before the Write Stash data is updated.

Note that Arm CPUs do not issue Write Stash transactions.

Configurations affected

Any CMN configuration.

Conditions

This erratum occurs when the following conditions are met:

- RN-I or RN-D issues AXI Write Stash transaction with a valid StashNID targeting a CPU cache
- RN-I or RN-D issues another AXI transaction after receiving the completion for the Write Stash. For example, PCIE MSI write or write to flag address
- The Stash CPU can observe the results of the second transaction above before the Write Stash data is updated for the first

Implications

If the conditions are met, Write Stash might receive early completion while the Stash CPU still has an old copy causing multi-copy atomicity issues.

Workarounds

The workaround is to send the result in Stash to the SLC instead of the CPU cache, by disabling stash snooping using `por_hnf_aux_ctl.hnf_stash_disable`.

3300058

More than two XY route override can result in deadlocks

Status

Affects: CI-700

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r1p0, r1p1, r1p2, r1p3, r2p0, r2p1, r2p2, r3p0, r3p1. Open.

Description

Default XY routing can be overridden by programming up to 16 sourceID or targetID pairs in the `por_mxp_xy_override_sel` registers. The sourceID or targetID pairs in indexes 0 and 1 are the only indexes that result in XY overrides, indexes >1 are ignored.

Configurations affected

All CI-700 configurations with the `XY_OVERRIDE_CNT > 2`.

Conditions

This occurs when the `por_mxp_xy_override_sel` registers with indexes > 1 are programmed with XY overrides.

Implications

If the conditions are met, either of the following will occur depending on if:

- The source or target pair is in an index > 1, the XY override behavior will not occur.
- Multiple MXPs require XY override programming and any MXP is in an index > 1, a deadlock will occur.

Workaround

Do not program `por_mxp_xy_override_sel` registers with indexes > 1, only 2 overrides are valid in CMN.

3658369

MPAM MSMON_CSU.NRDY not cleared in a finite time

Status

Affects: CI-700

Fault Type: Programmer Cat-B

Fault Status: Present in r0p0, r1p0, r1p1, r1p2, r1p3, r2p0, r2p1, r2p2, r3p0, r3p1. Open

Description

Once MSMON_CFG_CSU_FLT (Filter Register) and MSMON_CFG_CSU_CTL (Control Register) are programmed, expectation is that NRdy bit will clear in finite time. The bug is MSMON_CSU.NRdy bit does not get cleared.

Configurations affected

All configurations that use MPAM.

Conditions

This erratum occurs if all the following conditions are met:

- The configuration parameter CHI_MPAM_ENABLE is TRUE for the mesh
- MSMON_CFG_CSU_CTL.EN is set to 1'b1
- MSMON_CSU.NRDY is read to indicate hardware is done updating MSMON_CSU register.

Implications

Software cannot rely on the NRDY bit to indicate when the MSMON_CSU.VALUE is ready, and will fail all attempts to read the cache occupancy counters.

Workaround

After programming an MPAM monitor, wait for 1 micro-second to read MSMON_CSU register. After this period the NRDY bit can be ignored.

Category B (rare)

There are no errata in this category.

Category C

2177971

HN-I RAS syndrome registers do not capture correct opcode

Status

Affects: CI-700

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r1p1, r1p2,r1p3. Fixed in r2p0.

Description

The OPCODE field in the HN-I por_hni_errmisc RAS Syndrome register does not correctly capture the new REQ opcodes introduced in CHI-E.

Configurations Affected

All CI-700 configurations that use RAS error logging.

Conditions

A RAS error triggered by a new CHI-E transaction that causes the syndrome to be captured in the por_hni_errmisc register on a transaction processed by HN-I/P/D/V/T.

Implications

A read of the por_hni_errmisc.OPCODE field may return an incorrect opcode. The opcode does not properly reflect an error on a CHI-E opcode that has bit [6] set.

Workaround

RAS handler and software can use the following table indicating which por_hni_errmisc.OPCODE values are affected by aliasing due to this issue. If a RAS error involves opcodes listed as **Yes**, software can indicate that either opcode could have been the actual opcode involved in the error. Note that some cases with opcode[6]=0 are Reserved in the *CHI-E Specification*.

CHI-E REQ Opcodes			
Opcode[5:0]	Opcode[6]=0	Opcode[6]=1	Can Opcode[6]=1 RAS error happen at HN-X?
0x01	ReadShared	MakeReadUnique	Yes
0x02	ReadClean	WriteEvictOrEvict	No
0x03	ReadOnce	WriteUniqueZero	Yes
0x04	ReadNoSnP	WriteNoSnPZero	No
0x07	ReadUnique	StashOnceSepShared	No
0x08	CleanShared	StashOnceSepUnique	No
0x0C	MakeUnique	ReadPreferUnique	Yes
0x10	Reserved	WriteNoSnPFullCleanSh	No
0x11	ReadNoSnP-Sep	WriteNoSnPFullCleanInv	No
0x12	Reserved	WriteNoSnPFullCleanSh-PerSep	No
0x14	DVMOp	WriteUniqueFullCleanSh	Yes
0x16	Reserved (WriteCleanPtl)	WriteUniqueFullCleanSh-PerSep	Yes
0x18	WriteUniquePtl	WriteBackFullCleanSh	Yes
0x19	WriteUniqueFull	WriteBackFullCleanInv	Yes
0x1A	WriteBackPtl	WriteBackFullCleanSh-PerSep	Yes
0x1C	WriteNoSnPPtl	WriteCleanFullCleanSh	Yes
0x1E	Reserved	WriteCleanFullCleanSh-PerSep	Yes
0x20	WriteUniqueFullStash	WriteNoSnPPtlCleanSh	No
0x21	WriteUniquePtlStash	WriteNoSnPPtlCleanInv	No
0x22	StashOnceShared	WriteNoSnPPtlCleanSh-PerSep	No
0x24	ReadOnceCleanInvalid	WriteUniquePtlCleanSh	Yes
0x26	ReadNotSharedDirty	WriteUniquePtlCleanSh-PerSep	Yes

2741290

RAS HN-I and SBSX ERRGSR registers do not capture correct device instance information

Status

Affects: CI-700

Fault Type: Programmer Category C

Fault Status: r0p0, r1p0, r1p1, r1p2, r1p3, r2p0, r2p1, r2p2, r3p0, r3p1. Open.

Description

The CI Error Group Status Registers (ERRGSR) capture device instance error information for RAS events. The registers indicate the device instance within a device group. The registers are not updated correctly for the HN-I and SBSX device groups, so cannot be used to determine the device instances for RAS events.

Configurations Affected

All CI-700 configurations that use RAS error logging.

Conditions

A RAS event triggered by an HN-I or SBSX device.

Implications

Software cannot use the HN-I or SBSX ERRGSR registers.

Workaround

The RAS handler must read the individual HN-I and SBSX instance RAS logging registers when RAS interrupts occur.

3013642

Incorrect TagMatch response on partial writes with MTE Match

Status

Affects: CI-700

Fault Type: Programmer Category C

Fault Status: r0p0, r1p0, r1p1, r1p2, r1p3, r2p0, r2p1, r2p2, r3p0, r3p1. Open.

Description

Partial Write requests with MTE TagOp Match can cause an incorrect TagMatch response

Configurations affected

Any configuration with HN-F devices that use MTE without MTSX

Conditions

This erratum occurs when the following conditions are met:

- Non-Arm CPU issues non-allocating WriteUniquePtl with TagOp=Match and Tag=<partial>
- The System Level Cache has dirty data but without MTE Tag
- HN-F incorrectly responds with no TagMatch for the WriteUniquePtl

Implications

If the conditions are met, MTE Write Partial transactions that require TagMatch response can be incorrect. Partial write transactions might not respond with TagMatch.

Workarounds

No workaround required for Arm CPUs or configurations with MTSX, Arm CPUs do not issue Write Partial with TagMatch.

3031700

Debug reads with simultaneous coherent traffic or dynamic power transitions can cause deadlock

Status

Affects: CI-700

Fault Type: Programmer Category C

Fault Status: r0p0, r1p0, r1p1, r1p2, r1p3, r2p0, r2p1, r2p2, r3p0, r3p1. Open.

Description

HN-F System Level Caches (SLC) and Snoop Filter (SF) Debug Reads with simultaneous coherent traffic or dynamic power retention transitions can cause a deadlock.

Configurations affected

Any configuration.

Conditions

This erratum occurs when one of the following conditions are met:

- Coherent transactions that require HN-F Snoop Filter allocation while performing SLC or SF debug read
- Dynamic retention mode is enabled while performing a SLC or SF debug read

Implications

A deadlock can occur if the conditions are met. Note that expected usage is performing the Debug Reads in the absence of traffic since traffic can change the state of the RAMs.

Workaround

Use the following workarounds to prevent a deadlock:

- Stop CPU (RN-F) and IO (RN-I) coherent traffic before issuing Debug Reads
- Disable Dynamic retention power transitions via `por_hnf_ppu_pwpr.dyn_en = 1'b0` (reset value)

3114501

Transactions targeting the HN-D AXI interface might be stalled by a continuous stream of CMN configuration transactions

Status

Affects: CI-700

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r1p1, r1p2, r1p3, r2p0, r2p1, r2p2, r3p0, r3p1. Open.

Description

Transactions to a HN-D targeting the AXI interface might be stalled by a continuous stream of transactions targeting the CMN configuration space. This includes CMN configuration registers and transactions targeting the CMN AXU interfaces.

Configurations affected

All configurations.

Conditions

- Read or Write transactions are targeting the HN-D AXI interface.
- A continuous stream of transactions is targeting CMN configuration space. Examples of a continuous stream of transactions are a single CPU issuing reads or writes in a continuous loop, or multiple CPUs issuing reads in a polling loop, resulting in multiple outstanding transactions active in the HN-D continuously.

Implications

If the conditions are met, software that accesses CMN configuration space, including AXU interfaces, can create a denial-of-service scenario. This prevents transactions targeting the HN-D AXI interface from making progress.

Workaround

To prevent a continuous stream of transactions at the HN-D from occurring, serialize accesses to the CMN configuration space. For example, use polling loops to limit the number of CPUs accessing the CMN configuration space.

3197819

HN-I ERRADDR_NS.NS field is incorrect

Status

Affects: CI-700

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r1p1, r1p2, r1p3, r2p0, r2p1, r2p2, r3p0, r3p1. Open.

Description

The Non-Secure (NS) field within the NS version of the ERRADDR RAS register, `por_hni_erraddr_ns`, is incorrectly tied to 0. The register is used to indicate NS transaction error information, this field must always be 1.

Configurations affected

All CI-700 configurations.

Conditions

This erratum occurs when a HN-I NS RAS event occurs and the `por_hni_erraddr_ns` register is read.

Implications

If the conditions are met, the software cannot rely on the value of the `por_hni_erraddr_ns.ns` field and the NS register classification indicates a NS RAS event. Note that there are no other functional implications due to this issue, other than the incorrect value for the `por_hni_erraddr_ns.ns` bit.

Workaround

Ignore the `por_hni_erraddr_ns.ns` field value and rely on the NS classification of the register to determine NS RAS events.

3279821

HN-F Non-Secure RAS events may be reported in Secure error records

Status

Affects: CI-700

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r1p1, r1p2, r1p3, r2p0, r2p1, r2p2, r3p0, r3p1. Open.

Description

Under specific micro-architectural conditions, SLC Data RAM Single-Bit Error (SBE) or Double-Bit Error (DBE) for Non-Secure (NS) accesses can update the Secure RAS error records.

Configurations affected

CMN configurations with SLC_TAG_LATENCY = 1.

Conditions

This occurs when there is a SLC Data RAM SBE or DBE on a NS memory transaction.

Implications

If the conditions occur, Secure RAS error records may be updated for NS RAS events and a loss of RAS coverage for NS SBE and DBE errors.

Workaround

No workaround available, must assume Secure RAS error records were updated by NS RAS events, for example by checking the address to determine if it's in NS space.

Proprietary notice

This document is protected by copyright and other related rights and the use or implementation of the information contained in this document may be protected by one or more patents or pending patent applications. No part of this document may be reproduced in any form by any means without the express prior written permission of Arm Limited ("Arm"). No license, express or implied, by estoppel or otherwise to any intellectual property rights is granted by this document unless specifically stated.

Your access to the information in this document is conditional upon your acceptance that you will not use or permit others to use the information for the purposes of determining whether the subject matter of this document infringes any third party patents.

The content of this document is informational only. Any solutions presented herein are subject to changing conditions, information, scope, and data. This document was produced using reasonable efforts based on information available as of the date of issue of this document. The scope of information in this document may exceed that which Arm is required to provide, and such additional information is merely intended to further assist the recipient and does not represent Arm's view of the scope of its obligations. You acknowledge and agree that you possess the necessary expertise in system security and functional safety and that you shall be solely responsible for compliance with all legal, regulatory, safety and security related requirements concerning your products, notwithstanding any information or support that may be provided by Arm herein. In addition, you are responsible for any applications which are used in conjunction with any Arm technology described in this document, and to minimize risks, adequate design and operating safeguards should be provided for by you.

This document may include technical inaccuracies or typographical errors. THIS DOCUMENT IS PROVIDED "AS IS". ARM PROVIDES NO REPRESENTATIONS AND NO WARRANTIES, EXPRESS, IMPLIED OR STATUTORY, INCLUDING, WITHOUT LIMITATION, THE IMPLIED WARRANTIES OF MERCHANTABILITY, SATISFACTORY QUALITY, NON-INFRINGEMENT OR FITNESS FOR A PARTICULAR PURPOSE WITH RESPECT TO THE DOCUMENT. For the avoidance of doubt, Arm makes no representation with respect to, and has undertaken no analysis to identify or understand the scope and content of, any patents, copyrights, trade secrets, trademarks, or other rights.

TO THE EXTENT NOT PROHIBITED BY LAW, IN NO EVENT WILL ARM BE LIABLE FOR ANY DAMAGES, INCLUDING WITHOUT LIMITATION ANY DIRECT, INDIRECT, SPECIAL, INCIDENTAL, PUNITIVE, OR CONSEQUENTIAL DAMAGES, HOWEVER CAUSED AND REGARDLESS OF THE THEORY OF LIABILITY, ARISING OUT OF ANY USE OF THIS DOCUMENT, EVEN IF ARM HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

Reference by Arm to any third party's products or services within this document is not an express or implied approval or endorsement of the use thereof.

This document consists solely of commercial items. You shall be responsible for ensuring that any permitted use, duplication or disclosure of this document complies fully with any relevant export laws and regulations to assure that this document or any portion thereof is not exported, directly or indirectly, in violation of such export laws. Use of the word "partner" in reference to Arm's customers is not intended to create or refer to any partnership relationship with any other company. Arm may make changes to this document at any time and without notice.

This document may be translated into other languages for convenience, and you agree that if there is any conflict between the English version of this document and any translation, the terms of the English version of this document shall prevail.

The validity, construction and performance of this notice shall be governed by English Law.

The Arm corporate logo and words marked with ® or ™ are registered trademarks or trademarks of Arm Limited (or its affiliates) in the US and/or elsewhere. Please follow Arm's trademark usage guidelines at <https://www.arm.com/company/policies/trademarks>. All rights reserved. Other brands and names mentioned in this document may be the trademarks of their respective owners.

Arm Limited. Company 02557590 registered in England.

110 Fulbourn Road, Cambridge, England CB1 9NJ.

(PRE-1121-V1.0)

Product and document information

Read the information in these sections to understand the release status of the product and documentation, and the conventions used in the Arm documents.

Product status

All products and Services provided by Arm require deliverables to be prepared and made available at different levels of completeness. The information in this document indicates the appropriate level of completeness for the associated deliverables.

Product completeness status

The information in this document is Final, that is for a developed product.

Product revision status

The rxpy identifier indicates the revision status of the product described in this manual, where:

rx

Identifies the major revision of the product.

py

Identifies the minor revision or modification status of the product.