



## CoreSight ETM-M55 TM981 Software Developer Errata Notice

This document contains all known errata since the r0p0 release of the product.

## Non-Confidential Proprietary notice

This document is protected by copyright and other related rights and the practice or implementation of the information contained in this document may be protected by one or more patents or pending patent applications. No part of this document may be reproduced in any form by any means without the express prior written permission of Arm.

**No license, express or implied, by estoppel or otherwise to any intellectual property rights is granted by this document unless specifically stated.**

Your access to the information in this document is conditional upon your acceptance that you will not use or permit others to use the information for the purposes of determining whether implementations infringe any third party patents.

THIS DOCUMENT IS PROVIDED "AS IS". ARM PROVIDES NO REPRESENTATIONS AND NO WARRANTIES, EXPRESS, IMPLIED OR STATUTORY, INCLUDING, WITHOUT LIMITATION, THE IMPLIED WARRANTIES OF MERCHANTABILITY, SATISFACTORY QUALITY, NON-INFRINGEMENT OR FITNESS FOR A PARTICULAR PURPOSE WITH RESPECT TO THE DOCUMENT. For the avoidance of doubt, Arm makes no representation with respect to, and has undertaken no analysis to identify or understand the scope and content of, patents, copyrights, trade secrets, or other rights.

This document may include technical inaccuracies or typographical errors.

TO THE EXTENT NOT PROHIBITED BY LAW, IN NO EVENT WILL ARM BE LIABLE FOR ANY DAMAGES, INCLUDING WITHOUT LIMITATION ANY DIRECT, INDIRECT, SPECIAL, INCIDENTAL, PUNITIVE, OR CONSEQUENTIAL DAMAGES, HOWEVER CAUSED AND REGARDLESS OF THE THEORY OF LIABILITY, ARISING OUT OF ANY USE OF THIS DOCUMENT, EVEN IF ARM HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

This document consists solely of commercial items. You shall be responsible for ensuring that any use, duplication or disclosure of this document complies fully with any relevant export laws and regulations to assure that this document or any portion thereof is not exported, directly or indirectly, in violation of such export laws. Use of the word "partner" in reference to Arm's customers is not intended to create or refer to any partnership relationship with any other company. Arm may make changes to this document at any time and without notice.

If any of the provisions contained in these terms conflict with any of the provisions of any click through or signed written agreement covering this document with Arm, then the click through or signed written agreement prevails over and supersedes the conflicting provisions of these terms. This document may be translated into other languages for convenience, and you agree that if there is any conflict between the English version of this document and any translation, the terms of the English version of the Agreement shall prevail.

The Arm corporate logo and words marked with ® or ™ are registered trademarks or trademarks of Arm Limited (or its subsidiaries) in the US and/or elsewhere. All rights reserved. Other brands and names mentioned in this document may be the trademarks of their respective owners. Please follow Arm's trademark usage guidelines at <http://www.arm.com/company/policies/trademarks>.

Copyright © 2021 Arm Limited (or its affiliates). All rights reserved.

Arm Limited. Company 02557590 registered in England.

110 Fulbourn Road, Cambridge, England CB1 9NJ.

LES-PRE-20349

## Confidentiality Status

This document is Non-Confidential. The right to use, copy and disclose this document may be subject to license restrictions in accordance with the terms of the agreement entered into by Arm and the party that Arm delivered this document to.

## Product Status

The information in this document is for a product in development and is not final.

## Web address

<http://www.arm.com/>.

## Feedback on this product

If you have any comments or suggestions about this product, contact your supplier and give:

- The product name.
- The product revision or version.
- An explanation with as much information as you can provide. Include symptoms and diagnostic procedures if appropriate.

## Feedback on this document

If you have comments on content then send an e-mail to [errata@arm.com](mailto:errata@arm.com) giving:

- The document title.
- The document number: SDEN-1679657.
- If applicable, the page number(s) to which your comments refer.
- A concise explanation of your comments.

Arm also welcomes general suggestions for additions and improvements.

# Contents

---

<i>INTRODUCTION</i>	5
<i>ERRATA SUMMARY TABLE</i>	7
<i>2080680</i> The ETM single-shot control and the ETM ViewInst start/stop control may fail to operate correctly	8

# Introduction

---

## Scope

This document describes errata categorized by level of severity. Each description includes:

- The current status of the erratum.
- Where the implementation deviates from the specification and the conditions required for erroneous behavior to occur.
- The implications of the erratum with respect to typical applications.
- The application and limitations of a workaround where possible.

## Categorization of errata

Errata are split into three levels of severity and further qualified as common or rare:

<b>Category A</b>	A critical error. No workaround is available or workarounds are impactful. The error is likely to be common for many systems and applications.
<b>Category A (Rare)</b>	A critical error. No workaround is available or workarounds are impactful. The error is likely to be rare for most systems and applications. Rare is determined by analysis, verification and usage.
<b>Category B</b>	A significant error or a critical error with an acceptable workaround. The error is likely to be common for many systems and applications.
<b>Category B (Rare)</b>	A significant error or a critical error with an acceptable workaround. The error is likely to be rare for most systems and applications. Rare is determined by analysis, verification and usage.
<b>Category C</b>	A minor error.

## Change control

Errata are listed in this section if they are new to the document, or marked as “updated” if there has been any change to the erratum text. Fixed errata are not shown as updated unless the erratum text has changed. The errata summary table on page 7 identifies errata that have been fixed in each product revision.

### 15-Sep-2021: Changes in document version 3.0

ID	Status	Area	Cat	Summary of erratum
No new or updated errata in this document version.				

### 23-Apr-2021: Changes in document version 2.0

ID	Status	Area	Cat	Summary of erratum
<a href="#">2080680</a>	New	Programmer	CatC	The ETM single-shot control and the ETM ViewInst start/stop control may fail to operate correctly

### 20-Dec-2019: Changes in document version 1.0

ID	Status	Area	Cat	Summary of erratum
No errata in this document version.				

## Errata summary table

---

The errata associated with this product affect product versions as below.

ID	Cat	Summary	Found in versions	Fixed in version
2080680	CatC	The ETM single-shot control and the ETM ViewInst start/stop control may fail to operate correctly	r0p0, r0p1, r0p2	r1p0

# Errata descriptions

## Category A

---

There are no errata in this category.

## Category A (rare)

---

There are no errata in this category.

## Category B

---

There are no errata in this category.

## Category B (rare)

---

There are no errata in this category.

## Category C

---

### 2080680

**The ETM single-shot control and the ETM ViewInst start/stop control may fail to operate correctly**

#### Status

Affects: CoreSight ETM-M55

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r0p1, r0p2. Fixed in r1p0.

#### Description

The CoreSight *Embedded Trace Macrocell* (CoreSight ETM-M55) supports the use of *Data Watchpoint and Trace Unit* (DWT) comparator inputs to drive trace filtering resources including single-shot and start/stop. This allows single-shot to fire when a particular instruction is executed or trace to start or stop on a particular instruction. This erratum can cause single-shot and start/stop to not occur.

#### Configurations affected

This erratum affects all configurations of the Cortex-M55 processor configured with the DWT and ETM.

#### Conditions

The erratum occurs if the following sequence of conditions are met:

1. The ETM is enabled and programmed to use a DWT comparator with a single-shot control or the ETM is enabled and programmed to use a DWT comparator for instruction based filtering using the ViewInst start/stop control.
2. The DWT comparator is configured to match on an instruction address and the instruction at that address is one of the following:
  - LDM
  - STM
  - Load instruction which loads the PC
  - BLXNS
  - An instruction that can trigger a function return such as BX LR



3. That instruction is executed by the processor

**Implications**

- ETM resources setup to use single-shot control will not operate as expected
- Instructions may not be traced
- More instructions may be traced than expected

**Workaround**

DWT comparators used by the ETM should be adjusted to avoid the instruction types listed in Conditions above.